Appendices

Tab Number	Description
Tab 1:	2012 SOAP Unauthorized Discharges
Tab 2:	Key - Measures Taken In Response to Unauthorized Discharges
Tab 3:	2012 Preventive Maintenance Map
Tab 4:	Sewer Mains Inspected In 2012 By Board
Tab 5:	Sewer Mains Inspected In 2012 By Contractors
Tab 6:	Sewer Mains Inspected In 2012 By Board and Contractors, No Duplicates
Tab 7:	Sewer Mains Inspected In 2012 By Board and Contractors, Including Duplicates
Tab 8:	Sewer Mains Inspected In Cycle: 6/23/09 – 6/22/17
Tab 9:	Sewer Mains Inspected In 2012 Utilizing CCTV
Tab 10:	Sewer Mains Inspected In 2012 Utilizing Smoke Testing
Tab 11:	Sewer Mains Cleaned In 2012 By Board
Tab 12:	Sewer Mains Cleaned In 2012 By Contractors
Tab 13:	Sewer Mains Cleaned In 2012 By Board and Contractors, No Duplicates
Tab 14:	Sewer Mains Cleaned In 2012 By Board and Contractors, Including Duplicates
Tab 15:	Sewer Mains Cleaned In Cycle: 6/23/08 – 6/22/18
Tab 16:	Sewer Manholes Inspected In 2012 By Board
Tab 17:	Sewer Manholes Inspected In 2012 By Contractors
Tab 18:	Sewer Manholes Inspected In 2012 By Board and Contractors, No Duplicates
Tab 19:	Sewer Manholes Inspected In 2012 By Board and Contractors,

	Including Duplicates
Tab 20:	Sewer Manholes Inspected In Cycle: 8/18/09 – 8/15/12
Tab 21:	Sewer Manholes Inspected In Cycle: 8/16/12 – 12/31/
Tab 22:	Sewer Collection System Repairs in 2012 By Board
Tab 23:	Sewer Collection System Repairs in 2012 By Contractors
Tab 24:	Sewer Collection System Repairs in 2012 By Board and Contractors
Tab 25:	2012 Preventive Maintenance Reports
Tab 26:	2012 Semi-Annual Inspections – Air Release Valves
Tab 27:	2012 Sewer Force Main Isolation Valves Exercise and Inspection
Tab 28:	2012 Sewer Force Main Alignment Inspection
Tab 29:	2012 Cathodic Protection Surveys
Tab 30:	2012 Eastbank Population Projection
Tab 31:	Original Consent Decree Accomplishments
Tab 32:	Modified Consent Decree Accomplishments